


**Embout MALE GAZ à souder**


<b>codice</b>	<b>G</b>	<b>B</b>	<b>C</b>	
	<b>inch</b>	<b>mm</b>	<b>mm</b>	<b>kg</b>
4.530.CB.01-A	1/8	10	20	0,01
4.530.CB.04-A	1/4	12	24	0,02
4.530.CB.05-A	3/8	12	24	0,04
4.530.CB.08-A	1/2	15	30	0,06
4.535.CB.08-A	1/2	15	50	0,10
4.531.CB.08-A	1/2	15	100	0,20
4.530.CB.10-A	3/4	15	30	0,10

<b>codice</b>	<b>G</b>	<b>B</b>	<b>C</b>	
	<b>inch</b>	<b>mm</b>	<b>mm</b>	<b>kg</b>
4.531.CB.10-A	$\frac{3}{4}$	15	100	0,20
4.530.CB.13-A	1	17	35	0,14
4.531.CB.13-A	1	17	100	0,25
4.530.CB.29-A	1 $\frac{1}{4}$	18	38	0,16
4.530.CB.38-A	1 $\frac{1}{2}$	20	40	0,20
4.530.CB.50-A	2	22	45	0,25
4.530.CB.65-A	2 $\frac{1}{2}$	23	50	0,35
4.530.CB.71-A	3	26	55	0,40
4.530.CB.75-A	3 $\frac{1}{2}$	26	55	0,50
4.530.CB.80-A	4	28	60	0,60