


	G	A	B	C	D	E	
	<i>inch</i>	<i>mm</i>	<i>mm</i>	<i>mm</i>	<i>mm</i>	<i>mm</i>	<i>kg</i>
2.100.AA.04 A	¼	10	28	65	91	47	0,30
2.100.AA.05 A	⅜	12	28	65	85	47	0,30
2.100.AA.08 A	½	15	35	64	85	50	0,40
2.100.AA.10 A	¾	20	40	67	85	53	0,55
2.100.AA.13 A	1	25	50	83	125	76	1,00
2.100.AA.29 A	1 ¼	32	57	79	125	80	1,70
2.100.AA.38 A	1 ½	40	70	103	140	88	2,00
2.100.AA.50 A	2	50	89	119	184	109	3,80
2.100.AA.65 A	2 ½	66	114	146	215	126	7,00
2.100.AA.71 A	3	80	140	150	245	148	10,00
2.100.AA.80 A	4	100	161	204	275	161	14,00



	G	A	B	C	D	E	
	<i>inch</i>	<i>mm</i>	<i>mm</i>	<i>mm</i>	<i>mm</i>	<i>mm</i>	<i>kg</i>
2.100.AA.04 A	¼	10	28	65	91	47	0,30
2.100.AA.05 A	⅜	12	28	65	85	47	0,30
2.100.AA.08 A	½	15	35	64	85	50	0,40
2.100.AA.10 A	¾	20	40	67	85	53	0,55
2.100.AA.13 A	1	25	50	83	125	76	1,00
2.100.AA.29 A	1 ¼	32	57	79	125	80	1,70
2.100.AA.38 A	1 ½	40	70	103	140	88	2,00
2.100.AA.50 A	2	50	89	119	184	109	3,80
2.100.AA.65 A	2 ½	66	114	146	215	126	7,00
2.100.AA.71 A	3	80	140	150	245	148	10,00
2.100.AA.80 A	4	100	161	204	275	161	14,00